



(MHz)

# Central Frequency (MHz)

123.2560  
123.2559  
123.2558  
123.2557  
123.2556  
123.2555  
123.2554  
123.2553  
123.2552  
123.2551  
123.2550




# SNR



# P-P/mean of single voxel (%)


(%)




# p2p/mean (%)

(%)

0.8  
0.7  
0.6  
0.5  
0.4  
0.3  
0.2  
0.1  
0




# SGR



8/14 (六) 停電一天，復電後MRI冰水循環系統閥門未正常開啟，造成  
8/16 (一) MRI冰水循環系統是處於溫度過高的情況下掃描，造成系統穩定度數值有所改變，後續則回復穩定

# Drift Rate



# He Level (%)

He (%)

95.0

90.0

85.0

80.0


75.0

70.0

65.0

60.0

55.0



2021/8/2

2021/8/3

2021/8/4

2021/8/5

2021/8/6

2021/8/7

2021/8/8

2021/8/9

2021/8/10

2021/8/11

2021/8/12

2021/8/13

2021/8/14

2021/8/15

2021/8/16

2021/8/17

2021/8/18

2021/8/19

2021/8/20

2021/8/21

2021/8/22

2021/8/23

2021/8/24

2021/8/25

2021/8/26

2021/8/27

2021/8/28

2021/8/29


2021/8/30

2021/8/31

# Ghosting (%)

(%)

1.00  
0.80  
0.60  
0.40  
0.20  
0.00



2021/8/2  
2021/8/3  
2021/8/4  
2021/8/5  
2021/8/6  
2021/8/7  
2021/8/8  
2021/8/9  
2021/8/10  
2021/8/11  
2021/8/12  
2021/8/13  
2021/8/14  
2021/8/15  
2021/8/16  
2021/8/17  
2021/8/18  
2021/8/19  
2021/8/20  
2021/8/21  
2021/8/22  
2021/8/23  
2021/8/24  
2021/8/25  
2021/8/26  
2021/8/27  
2021/8/28  
2021/8/29  
2021/8/30  
2021/8/31